

DIMENSIONS



```
graph TD; DIMENSIONS --> Functional; DIMENSIONS --> Non-Functional; DIMENSIONS --> Auxiliary;
```

**Functional
Dimensions**
(Should be
Toleranced)




**Non-Functional
Dimensions**
(General Tolerances)

**Auxiliary
Dimensions**
(Should not be
toleranced)

Bilateral tolerance






Unilateral tolerance



Basic Size

Tolerance Grade

Examples:

for holes: 45 H8

for shafts: 40 f7

for fits : 40 H8/ f7




Fig. D1 Functional, non-functional, and auxiliary dimensions

Linear Dimensions


```
graph TD; A[Linear Dimensions] --> B[Size Dimensions]; A --> C[Location Dimension];
```

**Size
Dimensions**

**Location
Dimension**

Manufacturing Stages

(from dimensioning point of view)



- Primary Stages of the Production (Req. Dimensioning for primary production)
- Secondary Stages of the Production (Req. Dimensioning for secondary production)




Fig 03 Dimensioning for fabrication




Fig. 02
Dimensioning for sand casting





Fig. D4
Dimensioning for machining

Surface texture symbols
(Machining symbols)


PLACEMENT OF DIMENSIONS

Some cautions should be taken into consideration while dimensioning:


1. Dimensions outside the view are preferred.
2. Dimensions should be applied to one view.
3. Dimensions should be placed on the view that shows the distance in its true length.
4. Dimension lines should be placed, in general 10 mm (1/2 in) away from the outlines of the view.
5. Parallel dimension lines should be placed uniformly.
6. Values should be midway (auto centered) between the arrow heads, except when a centerline interferes.
7. Dimensions arranged in continuous form are preferred upon readability.
8. Place a longer dimension line outside a shorter one.
9. Dimensions should never be crowded.
10. Center lines are used to indicate the symmetry, they should be considered as part of dimensioning.
11. All notes must be read horizontally.
12. Never use a center line, a line of a view, or an extension line as a dimension line.
13. Never allow outline of any kind to pass through a dimension line.
14. Avoid dimensioning to dashed lines if possible.




(a) CORRECT




(b) NO!




(c) NO!




(d) NO!




(a) CORRECT




(b) NO!




(a) CORRECT




(b) NO!




Omit unnecessary dimensions!




Toleranced Dimensions







Datum Dimensioning

Methods of Dimensioning of Cylinders:







Method of Dimensioning of a Square Prism:



or
→






or sq.
|
| square




↑
SI


↑
British

Dimensioning of a Sphere :




Representation of Holes





SI ref.


$\phi 10, \downarrow 15$




in British system
be

10 Drill, 15 Deep

Blind Hole






be 10 Drill - 18 c bore, 5 deep
in British system



$\phi 10, \sqcup \phi 18, \downarrow 5$

Counterbored Hole


10 Drill - 15 s'face, 2 Deep



$\phi 10, \sqcup \phi 15, \downarrow 2$



Spot faced Hole




$\phi 10, \vee \phi 18, 70^\circ$




be

10 drill - 70° c sink, 18 dia.




counter sink Hole

Method of Dimensioning Radii




SI




British


if there is a free space to indicate the dimension




if no




Dimension line is always directed towards the center of the arc and should be finished with one arrowhead only that touches the curve.




Dimensioning of a Tapered Feature:



Dimensioning of a Chamfer:



or →



Dimensioning Repeated Features:

